

Project Background

- The 2006 Madison Water Utility Master Plan identified a fire flow capacity deficiency and a lack of supply redundancy in the southern part of Pressure Zone 4.
- New Well 31 was recommended within zone 4.
- Two test wells were drilled
- Tradewinds Property
- Dairy Drive
- Both yielded similar capacity's and quality and 4901 Tradewinds Parkway was purchased





















